


Back counterbore (circular) milling



KTH Industriell teknik och management



The tool must be small enough to enter through the hole and, at the same time, have a sufficient ratio between the tool diameter and the shaft diameter in order to allow the necessary radial cutting depth.

